Form detail

#157: Weekly Report #25 - October 5 - 11, 2026

Forms

Location	
Form date	Oct 13, 2026
Template	Project Status Report
Description	Redvers WTP Upgrade - Weekly Report #25
Due date	Oct 13, 2026
Submitted by	Jordan Gent
Submitter's company	CCR Construction Ltd
Status	Closed
Last update	Oct 23, 2026, 3:56 PM CST
Last updated by	Jordan Gent
Included references	Assets | Files | Forms | Issues | Photos | File Packages | Sheets | Submittals | RFIs | PCOs | Schedule Activities

1. Monday

1.1 Date
October 5, 2026

1.2 Work Completed
Forming up loading dock grade beam, install exterior cladding, painting windows and door frames

Photos (5)

IMG_5885
Added as Reference
Taken on Oct 5, 2026, 12:29 PM CST
Added on Oct 5, 2026, 6:40 PM CST
Added by Jeff Anderson

IMG_5881
Added as Reference
Taken on Oct 5, 2026, 12:28 PM CST
Added on Oct 5, 2026, 6:40 PM CST
Added by Jeff Anderson

IMG_5890
Added as Reference
Taken on Oct 5, 2026, 5:16 PM CST
Added on Oct 5, 2026, 6:40 PM CST
Added by Jeff Anderson

IMG_5886
Added as Reference
Taken on Oct 5, 2026, 12:29 PM CST
Added on Oct 5, 2026, 6:40 PM CST
Added by Jeff Anderson

IMG_5884
Added as Reference
Taken on Oct 5, 2026, 12:29 PM CST
Added on Oct 5, 2026, 6:40 PM CST
Added by Jeff Anderson

2. Tuesday

2.1 Date
October 6, 2026

2.2 Work Completed
Clean out reservoir, form access hatches, painting window and door frames, install exterior finishes, install window glazing

Photos (7)

IMG_5912
Added as Reference
Taken on Oct 6, 2026, 5:02 PM CST
Added on Oct 6, 2026, 7:22 PM CST
Added by Jeff Anderson

IMG_5911
Added as Reference
Taken on Oct 6, 2026, 5:02 PM CST
Added on Oct 6, 2026, 7:22 PM CST
Added by Jeff Anderson



IMG_5905
Added as Reference
Taken on Oct 6, 2026, 2:31 PM CST
Added on Oct 6, 2026, 7:22 PM CST
Added by Jeff Anderson

IMG_5908
Added as Reference
Taken on Oct 6, 2026, 5:00 PM CST
Added on Oct 6, 2026, 7:22 PM CST
Added by Jeff Anderson

IMG_5910
Added as Reference
Taken on Oct 6, 2026, 7:22 PM CST
Added on Oct 6, 2026, 7:22 PM CST
Added by Jeff Anderson

IMG_5898
Added as Reference
Taken on Oct 6, 2026, 9:19 AM CST
Added on Oct 6, 2026, 7:22 PM CST
Added by Jeff Anderson

IMG_5907
Added as Reference
Taken on Oct 6, 2026, 4:59 PM CST
Added on Oct 6, 2026, 7:22 PM CST
Added by Jeff Anderson

3. Wednesday

3.1 Date
October 7, 2026

3.2 Work Completed
Access hatch formwork, installing window glazing, install exterior cladding

Photos (11)



IMG_5921
Added as Reference
Taken on Oct 7, 2026, 12:50 PM CST
Added on Oct 7, 2026, 7:03 PM CST
Added by Jeff Anderson

IMG_5929
Added as Reference
Taken on Oct 7, 2026, 5:33 PM CST
Added on Oct 7, 2026, 7:03 PM CST
Added by Jeff Anderson

IMG_5924
Added as Reference
Taken on Oct 7, 2026, 12:51 PM CST
Added on Oct 7, 2026, 7:03 PM CST
Added by Jeff Anderson

IMG_5928
Added as Reference
Taken on Oct 7, 2026, 7:03 PM CST
Added on Oct 7, 2026, 7:03 PM CST
Added by Jeff Anderson



IMG_5927
Added as Reference
Taken on Oct 7, 2026, 5:29 PM CST
Added on Oct 7, 2026, 7:03 PM CST
Added by Jeff Anderson

IMG_5926
Added as Reference
Taken on Oct 7, 2026, 7:03 PM CST
Added on Oct 7, 2026, 7:03 PM CST
Added by Jeff Anderson

IMG_5925
Added as Reference
Taken on Oct 7, 2026, 7:03 PM CST
Added on Oct 7, 2026, 7:03 PM CST
Added by Jeff Anderson

IMG_5922
Added as Reference
Taken on Oct 7, 2026, 12:51 PM CST
Added on Oct 7, 2026, 7:03 PM CST
Added by Jeff Anderson

IMG_5923
Added as Reference
Taken on Oct 7, 2026, 12:51 PM CST
Added on Oct 7, 2026, 7:03 PM CST
Added by Jeff Anderson

IMG_5918
Added as Reference
Taken on Oct 7, 2026, 12:47 PM CST
Added on Oct 7, 2026, 7:03 PM CST
Added by Jeff Anderson

IMG_5919
Added as Reference
Taken on Oct 7, 2026, 12:47 PM CST
Added on Oct 7, 2026, 7:03 PM CST
Added by Jeff Anderson

4. Thursday

4.1 Date
October 8, 2026

4.2 Work Completed
Cleaning out reservoir, access hatch install

5. Friday

5.1 Date
October 9, 2026

5.2 Work Completed
N/A

6. Saturday/Sunday

6.1 Date
October 10 - 11, 2026

6.2 Work Completed
N/A