Form detail

#172: Weekly Report #29 - November 2 - 8, 2026

Forms

Location	
Form date	Nov 9, 2026
Template	Project Status Report
Description	Redvers WTP Upgrade - Weekly Report #29
Due date	Nov 9, 2026
Submitted by	Jordan Gent
Submitter's company	CCR Construction Ltd
Status	Closed
Last update	Nov 10, 2026, 8:12 AM CST
Last updated by	Jordan Gent
Included references	Assets | Files | Forms | Issues | Photos | File Packages | Sheets | Submittals | RFIs | PCOs | Schedule Activities

1. Monday

1.1 Date
November 2, 2026

1.2 Work Completed
Stripping forms from access hatches and cleaning of dry pits

Photos (5)




IMG_6131
Added as Reference
Taken on Nov 2, 2026, 4:54 PM CST
Added on Nov 2, 2026, 6:59 PM CST
Added by Jeff Anderson



IMG_6127
Added as Reference
Taken on Nov 2, 2026, 6:59 PM CST
Added on Nov 2, 2026, 6:59 PM CST
Added by Jeff Anderson



IMG_6128
Added as Reference
Taken on Nov 2, 2026, 4:54 PM CST
Added on Nov 2, 2026, 6:59 PM CST
Added by Jeff Anderson



IMG_6125
Added as Reference
Taken on Nov 2, 2026, 4:52 PM CST
Added on Nov 2, 2026, 6:59 PM CST
Added by Jeff Anderson



IMG_6132
Added as Reference
Taken on Nov 2, 2026, 6:59 PM CST
Added on Nov 2, 2026, 6:59 PM CST
Added by Jeff Anderson

2. Tuesday

2.1 Date
November 3, 2026

2.2 Work Completed
Cleaning our dry pits and formwork from the loading dock slab and stairs

Photos (4)




IMG_6163
Added as Reference
Taken on Nov 3, 2026, 4:33 PM CST
Added on Nov 3, 2026, 7:06 PM CST
Added by Jeff Anderson



IMG_6164
Added as Reference
Taken on Nov 3, 2026, 4:33 PM CST
Added on Nov 3, 2026, 7:06 PM CST
Added by Jeff Anderson



IMG_6162
Added as Reference
Taken on Nov 3, 2026, 4:32 PM CST
Added on Nov 3, 2026, 7:06 PM CST
Added by Jeff Anderson



IMG_6159
Added as Reference
Taken on Nov 3, 2026, 7:06 PM CST
Added on Nov 3, 2026, 7:06 PM CST
Added by Jeff Anderson

3. Wednesday

3.1 Date
November 4, 2026

3.2 Work Completed
Formwork for loading dock slab and stairs, cleaning out dry pits and begin cleaning new reservoir

Photos (5)



IMG_6172
Added as Reference
Taken on Nov 4, 2026, 5:59 PM CST
Added on Nov 4, 2026, 5:59 PM CST
Added by Jeff Anderson



IMG_6174
Added as Reference
Taken on Nov 4, 2026, 5:05 PM CST
Added on Nov 4, 2026, 5:59 PM CST
Added by Jeff Anderson



IMG_6175
Added as Reference
Taken on Nov 4, 2026, 5:59 PM CST
Added on Nov 4, 2026, 5:59 PM CST
Added by Jeff Anderson



IMG_6177
Added as Reference
Taken on Nov 4, 2026, 5:59 PM CST
Added on Nov 4, 2026, 5:59 PM CST
Added by Jeff Anderson



IMG_6171
Added as Reference
Taken on Nov 4, 2026, 5:05 PM CST
Added on Nov 4, 2026, 5:59 PM CST
Added by Jeff Anderson

4. Thursday

4.1 Date
November 5, 2026

4.2 Work Completed
Install reinforcing for loading dock slab and stairs, reform generator pad at community centre, prep exterior doors for installation, drop off pump motors, survey pipes for existing locations for planning new tie ins

Photos (4)



IMG_6182
Added as Reference
Taken on Nov 5, 2026, 4:51 PM CST
Added on Nov 5, 2026, 8:59 PM CST
Added by Jeff Anderson



IMG_6183
Added as Reference
Taken on Nov 5, 2026, 4:52 PM CST
Added on Nov 5, 2026, 8:59 PM CST
Added by Jeff Anderson



IMG_6179
Added as Reference
Taken on Nov 5, 2026, 4:50 PM CST
Added on Nov 5, 2026, 8:59 PM CST
Added by Jeff Anderson



IMG_6180
Added as Reference
Taken on Nov 5, 2026, 4:51 PM CST
Added on Nov 5, 2026, 8:59 PM CST
Added by Jeff Anderson

5. Friday

5.1 Date
November 6, 2026

5.2 Work Completed
N/A

6. Saturday/Sunday

6.1 Date
November 7 - 8, 2026

6.2 Work Completed
N/A